



# UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE  
United States Patent and Trademark Office  
Address: COMMISSIONER FOR PATENTS  
P.O. Box 1450  
Alexandria, Virginia 22313-1450  
[www.uspto.gov](http://www.uspto.gov)

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/690,657	03/02/2001	Thomas C. Thompson		3470
7590	02/19/2010		EXAMINER	
Thomas C. Thompson 92-543 Kokole PL Makakilo, HI 96707			WENDELL, MARK R	
			ART UNIT	PAPER NUMBER
			3635	
			MAIL DATE	DELIVERY MODE
			02/19/2010	PAPER

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.



UNITED STATES DEPARTMENT OF COMMERCE  
U.S. Patent and Trademark Office  
Address: COMMISSIONER FOR PATENTS  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

APPLICATION NO./ CONTROL NO.	FILING DATE	FIRST NAMED INVENTOR / PATENT IN REEXAMINATION	ATTORNEY DOCKET NO.
09690657	3/2/2001	THOMPSON, THOMAS C.	

EXAMINER

Thomas C. Thompson  
92-543 Kokole PL  
Makakilo, HI 96707

MARK R. WENDELL

ART UNIT	PAPER
----------	-------

3635                  20100212

DATE MAILED:

Please find below and/or attached an Office communication concerning this application or proceeding.

Commissioner for Patents

Mr. Thompson,

Multiple phone calls have been placed and no return call has been made, so this letter is being sent to clarify the outstanding issues with your application so the necessary changes can be made and the patent can be printed. The case is still in condition for allowance; however these issues need to be resolved before the patent can be printed.

- 1) A new set of drawings needs to be submitted. The current drawings on file have hole punch marks and stamps through some of the data within the drawings. A new set should be submitted without the stamped data and hole punch marks.
- 2) Figures 27 and 29 appear in the drawings, but not in the brief description. Either the Figures should be removed from the application or language should be inserted into the specification that briefly describes these Figures.
- 3) Figures 27E, 29C and 37B are in the brief description; however they do not exist within the drawings. The language within the specification regarding these drawings should be removed.
- 4) Two Figure 38's exist within the drawings. This issue should be resolved.

Please feel free to contact me directly at 571-270-3245 with any questions. If these issues can be resolved without a conversation, feel free to fax the changes to me directly at 571-270-4245. Again, these issues need to be resolved ASAP so the patent can be printed.

Thank you,  
Mark Wendell

/Richard E. Chilcot, Jr./  
Supervisory Patent Examiner, Art Unit 3635